



2nd Generation Li-Ion Battery Pack 4067.2



Compatible with Ikelite DS161, DS160, and DS125 Strobes, this state of the art battery technology produces over 450 full power flashes with 1.4 second recycle times. Production is barely keeping up with demand so it presently takes about ONE MONTH to fill orders for the [2nd Generation Li-Ion Pack](#) (4067.2) and Li-Ion versions of the [DS160](#) (4060.4) and [DS161](#) (4061.4). If needed sooner, the lower priced [NiMH Battery Pack](#) (4066.5) is available.

Choose the proper charger as they are NOT interchangeable. New Smart Charger (4067.3) is correct for the 2nd Generation Li-Ion Battery Pack. The original Li-Ion Smart Charger (4067.1) is not suitable for the 2nd Generation Battery Pack. Choose Smart Charger (4066.1) for the NiMH Battery Pack.

Replacement Mounting Toggle for Strobe Battery Packs



Black Toggle Kit for NiMH / NiCad Packs (9457.63)
Gray Toggle Kit for Li-ion Packs (9457.64)
US\$9.00 each, Dealer Price

Toggles bear the brunt of the force required to waterproof the DS161, DS160, and DS125 Strobes and may wear out after years of opening and closing. To reduce this strain, we recommend customers detach the battery pack from the strobe front prior to storing for extended periods of time. The o-ring and receptacles can be protected using a [Battery Cover](#) (0591.4).

In the event the battery pack toggle has broken, replacement toggle kits are available as priced above. A 1/4" nut driver is required to replace a battery pack toggle (not included).

Non-functioning Li-Ion Battery Packs



Airline regulations dictate that a non-functioning or faulty Li-ion battery pack must NOT be shipped via air, and thus cannot be sent to Ikelite for repair service. Therefore, the following Ikelite policy applies to Li-ion battery packs, such as the original 1st Generation Li-Ion Battery Pack (4067), if it no longer accepts a charge.

1st Generation Li-ion Battery Packs (4067) LESS THAN 15 MONTHS OLD with a warranty defect qualify for a replacement 2nd Generation Li-ion Battery Pack (4067.2) AND compatible Smart Charger (4067.3) at No Charge. The date code on the top of the battery is the confirming date if no original purchase receipt is available.

1st Generation Li-ion Battery Packs (4067) LESS THAN 36 MONTHS OLD (out of warranty) not accepting a charge qualify for a replacement 2nd Generation Li-ion Battery (4067.2) at US\$200 Dealer Price, plus FREE compatible Smart Charger (4067.3)

1. Verify the original Li-ion Battery Pack (4067) no longer functions properly
2. After confirmation, disable the Battery Pack rather than ship it to Ikelite. Do so by removing and then breaking the power setting switch from the side of the Pack.
3. Take a picture showing both the broken switch and date code on the Battery Pack. Provide a copy of the original purchase receipt if noticeably different from the date code.
4. On your next order, submit this picture with your order request for the replacement 2nd Generation Li-ion Battery Pack (4067.2) along with compatible charger (4067.3).
5. Follow proper disposal procedures in your region for the original battery and charger. The old charger is NOT compatible with the 2nd Generation Battery.

Properly functioning batteries do NOT qualify for the above replacements. This is NOT a publicized trade-in program for batteries.

Thank you for the continued support.

Regards,

Duane Brigham
Ikelite Underwater Systems
ikelite.com